

VISUAL TANK INSPECTION REPORT

/essel
Port/Terminal:
Product/Cargo:

ETT-112

HERCULES/FREEPORT, TX

NORMAL BUTANOL

Your Reference: Our Reference:

Our Reference: FP/97-5024

Date

: 1-10-97

ank			-	
lumber	1C	2C	3C	
'ank				
!oating	MILD STEEL	MILD STEEL	MILD STEEL	
ast				
largo	CYCLOHEXANE	CYCLOHEXANE	CYCLOHEXANE	
econd Last	· · · · · · · · · · · · · · · · · · ·			
Cargo				
hird Last				
Cargo				·
isual Cleanliness				
Accepted *	ACCEPTED	ACCEPTED	ACCEPTED	
isual Cleanliness				
Rejected *				
ime/Date				
Inspected	1355 / 1-10-97	1355 / 1-10-97	1355 / 1-10-97	

ethod said to have been used to clean tanks: <u>ALL CARGO TANKS & PIPELINES WERE STRIPPED AND ALL TANKS WERE BLOWN FOR HIRTY-FIVE MINUTES EACH, AND VENTED FOR SIX HOURS.</u>

nformation regarding previous cargoes, tank coating and cleaning method was obtained from vessel personnel and cannot be uaranteed as accurate by Caleb Brett U.S.A., Inc. and no liability can be assumed for errors resulting from improper nformation supplied. This report, of necessity, is based on such information.

The cleanliness of inspected tank(s) is/are based on visual inspection of tank surfaces and line system at accessible areas only. This document does not cover the cleanliness of tank surfaces and line system at inaccessible spots and/or possible release of components of previous cargoes during loading, discharge or transport of the cargo in question, for which the vessel is fully responsible. Suitability of tank coating for intended cargo must be guaranteed by vessel's owner or by suppliers of the coating.

I T S-Caleb Brett